

### Continuous Radon Monitor

Model Number: 1028  
Calibration Date: 01/13/2016  
Monitor Time: 1/21/2005 1:1

Serial Number: 89284032  
CF: 2.90

### Inspection Company

Pro Check Inspections  
5632 Condor Dr  
Unit 4  
Fort Collins, CO-80525  
Phone Number: 970-227-6898  
License Number:

### Billing Information

### Site Information

### Site & Condition


Wind: NA  
Year Built: NA  
Mitigation System: Not Installed  
SqFt: NA

Atmospheric Condition: NA  
Structure Type: NA  
Monitor Location: NA

### Test Summary

Start Time: 01/12/2005 18:18  
End Time: 01/14/2005 18:18  
Measurement Interval(hr): 1.0  
Exposure Time: 2 Days 0 hrs

Overall Avg: 4.2 pCi/l  
EPA Avg: 4.1 pCi/l



\*\*\*\*\* 01/12/2005 \*\*\*\*\*

Time	Counts pCi/l	Flags
19:18	3.1	
20:18	8.3	
21:18	7.6	
22:18	4.5	
23:18	2.8	

\*\*\*\*\* 01/13/2005 \*\*\*\*\*

Time	Counts pCi/l	Flags
00:18	5.2	
01:18	3.8	
02:18	3.8	
03:18	3.1	
04:18	3.1	
05:18	3.8	
06:18	2.4	
07:18	0.7	
08:18	3.1	
09:18	2.1	
10:18	3.8	
11:18	1.7	
12:18	5.5	
13:18	2.1	
14:18	3.4	
15:18	3.4	
16:18	5.2	
17:18	3.4	
18:18	4.1	
19:18	5.9	
20:18	5.2	
21:18	3.4	
22:18	2.8	
23:18	5.9	

\*\*\*\*\* 01/14/2005 \*\*\*\*\*

Time	Counts pCi/l	Flags
00:18	6.5	
01:18	3.8	
02:18	5.9	
03:18	2.4	
04:18	2.1	
05:18	1.7	
06:18	0.7	
07:18	4.1	
08:18	2.8	

\*\*\*\*\* 01/14/2005 \*\*\*\*\*

Time	Counts pCi/l	Flags
09:18	2.8	
10:18	3.1	
11:18	5.2	
12:18	4.8	
13:18	8.6	
14:18	6.9	
15:18	9.3	
16:18	6.9	
17:18	7.2	
18:18	5.2	

Error Flags:

M Motion:

Inspector Signature \_\_\_\_\_

PC Software Version: 2.2.0

Embedded Software Version: 109